



Comprehensive engine coverage comparison (TFE731 engines and GTCP 36-100 and 36-150 APUs)

ROUTINE INSPECTION	EAP	MSP	MSP Gold
Routine inspection labor	●		●
Routine inspection parts	●	●	●
On condition maintenance	●	●	●
Engine health trend monitoring	●	●	●
S.O.A.P. kit and analysis	●	●	●
OTHER INSPECTIONS (MPI/CZI/HSI)	EAP	MSP	MSP Gold
Inspection labor	●	●	●
Consumable parts (does not include oil)	●	●	●
Component repair labor	●	●	●
Life limited parts	●	●	●
Engine removal and reinstallation	●		●
Shipment of engine	●		●
Rental engine/APU during CZI/HSI	●	●	●
UNSCHEDULED MAINTENANCE	EAP	MSP	MSP Gold
Field service repair teams	●	●	●
Component repair labor	●	●	●
Troubleshooting labor allowance	●	●	●
Consumable parts (does not include oil)	●	●	●
Other required parts	●	●	●
Logistical support for road trips	●		●
Rental engines	●	●	●
Exchange engine/Line Replaceable Unit (LRU)	●	●	●
Engine and LRU removal and reinstallation	●		●
Shipment of unserviceable engine or LRU	●		●
FOD gap coverage	●	●	●
OTHER BENEFITS	EAP	MSP	MSP Gold
Program transferable at time of sale	●	●	●
75 hour per year minimums for all clients	●		
Service bulletins: category 1, 2 and 3	●	●	●
Engine programs increase resale value	●	●	●