



# EAP's comprehensive engine coverage

(TAY 611-8 engines and GTCP 36-100G and 36-150G APUs)

EAP's COMPREHENSIVE ENGINE COVERAGE INCLUDES	Engine	APU
Labor and materials costs for regular engine shop visits (unscheduled, mid-life, overhaul)	●	●
Recommended and mandatory service bulletins	●	●
Line Replaceable Unit (LRU)	●	●
Rental engines during scheduled or unscheduled engine removals	●	●
Removal and re-installation labor for loaner engines	●	●
Inclusion of all airworthiness directives	●	●
Scheduled boroscopes	●	●
Engine health trend monitoring	●	N/A
Life limited parts	●	●
LRU removal and re-installation	●	●
Troubleshooting labor	●	●
Recovery worldwide of engines during covered event	●	●
Logistical support for road trips	●	●
Mobile repair team labor and travel	●	●
Mandatory and recommended service bulletins	●	●
Annual training course for one individual	●	●
Scheduled and unscheduled engine shop visits	●	●
All labor and subcontract charges	●	●
Corrosion and erosion	●	●
Technical publications	●	●
Service engineering	●	●
Access to over 80 EAP authorized service vendors	●	●

OTHER BENEFITS OF EAP	Engine	APU
Personalized customer service	●	●
Program transferable at time of sale	●	●
Replacement of oil at engine change	●	●

Visit [eap.aero](http://eap.aero) to learn more about our program, or call 214.350.0877.